

ALC, CIBC & 1621





New Facility

Two phase project to construct new facility on existing ALC site combining ALC, CIBC and 1621 programs. Demolish existing ALC and CIBC buildings keeping the Administration Building.

Budget

\$8,200,000

ALC, CIBC & 1621















ALC, CIBC & 1621






















Left desk Right desk


Renovate Office & Reception

Campus lacks appropriate reception counter. Remove storage and expand Office.

Budget

\$200,000








View from entry

Remove storage to expand reception area for two staff









Replace Walk-in Cooler & Freezer

Cooler and Freezer units have exceeded their useful life.

Budget

\$175,000





Replace Roof


Roof has exceeded its useful life.

Budget

\$1,900,000

Beasley Elementary









Replace Walk-in Cooler & Freezer

Cooler and Freezer units have exceeded their useful life.

Budget

\$175,000



BOTTOM EDGE OF ENTRY CANOPY IS TOO LOW AT THE DOOR AND IS A CODE VIOLATION



Replace Entry Canopy

Current canopy is too low to meet code requirements.

Budget

\$100,000



DEMO STAGE FOR ADDITIONAL SEATING

EXPAND CAFETERIA KITCHEN
AND SERVING LINES






Enlarge Cafeteria & Remove Stage

Cafeteria needs to expand to accommodate the student enrollment. School has main stage in Gymnasium.


Budget

\$300,000



Serving exit

Serving entry





Renovate Kitchen Serving Lines

Serving lines cannot accommodate student enrollment during lunch periods.

Budget

\$325,000





Parking off of street into mud. There is no curb.



Remove trees and pave for 20 spaces.



Overflow parking on non-district land

Expand Parking 25 Spaces

Parking capacity does not meet needs for current student enrollment.

Budget

\$475,000

Brazos Crossing Admin.



Mismatched brick and window panels



Moisture penetration behind brick



Gap between window and frame






Replace Exterior Brick and Curtainwall


Exterior window wall leaks throughout the 40-year old building, damaging structure.

Budget

\$1,800,000

Briscoe Junior











Replace Carpet

Carpet has exceeded its useful life.

Budget

\$650,000














Replace Carpet

Carpet has exceeded its useful life.

Budget

\$325,000

Campbell Elementary










Replace Interior Vinyl Wallcovering

Vinyl Wallcovering has exceeded its useful life.

Budget

\$115,000

Foster High





1'x1' Locker



2'x6' Locker



Bond2017 LAMAR CONSOLIDATED ISD

Replace lockers in Athletic Fieldhouse

18 year old lockers have failed and are not secure.

Locker Count

1'x1' = 520

1'x3' = 320

1.5'x3' = 300


2'x6' = 70 Varsity


2'x6' = 70 JVarsity

Budget

\$350,000

Foster High












Replace Carpet


Carpet has exceeded its useful life.

Budget

\$750,000

Foster High










Renovate Classrooms to LOTE Lab

Repurpose two existing classrooms for Language Other Than English (LOTE) lab. Current classrooms do not meet program requirements.

Budget

\$350,000

George Junior










Renovate Forum

Renovate the Forum, including stage with curtain, new screen, carpet, VCT and new seats.

Budget

\$950,000

George Junior









Renovate Kitchen Serving Lines


Serving lines cannot accommodate student enrollment during lunch periods.

Budget

\$650,000

George Junior








Add Visitor Parking

Parking capacity does not meet needs of visitors and staff.

Budget

\$450,000

Huggins Elementary










Replace Walk-in Cooler & Freezer

Cooler and Freezer units have exceeded their useful life.

Budget

\$175,000

Jackson Elementary






Replace Carpet

Carpet has exceeded its useful life.

Budget

\$250,000

Jackson Elementary









Renovate Kitchen Serving Lines

Serving lines cannot accommodate student enrollment during lunch periods.

Budget

\$325,000

Jackson Elementary







Uneven surface constricts drainage

High spot prevents proper drainage





Improve Drainage in Parking Lots and Driveways


Water ponds in parking lots and driveways whenever it rains. Work would be coordinated with City street drainage.


Budget

\$125,000

Jane Long Elementary











Replace Carpet

Carpet in Building A has exceeded its useful life.

Budget

\$285,000

Jane Long Elementary









Restore Auditorium Seating

Original wood seats are deteriorating and need refinishing or replacement.

Budget

\$125,000

Jane Long Old Gym
















Renovate Facility for Current Programs

Original gymnasium requires complete renovation and restrooms brought into ADA compliance to house support staff.

Budget

\$3,200,000

Possible addition locations






Choir Room Addition

New 3,080 sf addition to house Choir program, which currently meets in regular classroom.

Budget

\$1,600,000





Renovate HVAC System in Old Section

Unit ventilators in old section of school do not meet current codes for noise control and fresh air.

Budget

\$3,250,000





Eliminate head-in parking and add a sidewalk



Create parent drop off lane

Revise Parent Drop-Off on Mustang Avenue

Provide drop-off area by removing head-in parking along Mustang Avenue.

Budget

\$140,000









Replace Intercom System

Intercom parts are no longer available to properly repair current system.

Budget

\$130,000

Lamar High Complex Site





Repave road and drainage

New sidewalk and curb along Mustang Ave.

New sidewalk and replace access road

Additional 20 parking

Improve Drainage, Drives Sidewalks & Parking

Repair site drainage issues, add sidewalks, repair paved areas and align driveways. Including: Development Center Building, Lamar CHS, Lamar JH, Traylor Stadium, and Transportation Dept.

Budget

\$2,500,000

Lamar High Complex Site




New sidewalk along Mustang Ave.





Mustang Ave.






Drainage issues at Development Center and parking.

Drainage issues under Football stands



Lamar High








Renovate Classrooms to LOTE Lab

Repurpose two existing classrooms for Language Other Than English (LOTE) lab. Current classrooms do not meet program requirements.

Budget

\$350,000










Replace Carpet

Carpet has exceeded its useful life.

Budget

\$300,000









Renovate Choir Room and Stage


Renovate to a usable stage with sound, lights and a curtain.

Budget

\$500,000



Possible addition location






New Orchestra Addition

1,680 sf addition to house new middle school Orchestra program.

Budget

\$1,100,000






Replace Intercom System

Intercom parts are not available to properly repair current systems.

Budget

\$100,000

Pink Elementary









Replace Carpet


Carpet has exceeded its useful life.

Budget

\$375,000

Pink Elementary










Replace Walk-in Cooler & Freezer

Cooler and Freezer units have exceeded their useful life.

Budget

\$175,000

Pink Elementary





Replace Interior Vinyl Wallcovering

Vinyl Wallcovering has exceeded its useful life.

Budget

\$120,000

Roberts Middle




New Orchestra Addition

1,680 sf addition to house new middle school Orchestra program.

Budget

\$1,100,000

Ryon Middle



Possible Addition location




New Orchestra Addition

1,680 sf addition to house new middle school Orchestra program.

Budget

\$1,100,000

Seguin Early Childhood









Replace Walk-in Cooler & Freezer

Cooler and Freezer units have exceeded their useful life.

Budget

\$175,000

Seguin Early Childhood





Replace Roof

Roof has exceeded its useful life.

Budget

\$1,900,000

Smith Elementary











Renovate Courtyard & Improve Drainage


Repave courtyard, remove grass, correct drainage and reconstruct walkway screen panels.

Budget

\$650,000

Taylor Ray Elementary







Replace Walk-in Cooler & Freezer

Cooler and Freezer units have exceeded their useful life.

Budget

\$175,000


Taylor Ray Elementary













Improve Drainage in Parking Lots

Improve drainage at the dropoff area and in the west side parking areas.

Budget

\$220,000

Terry High





Replace Wooden Bleachers at Football Field

Replace wooden bleachers to comply with ADA requirements.






Budget

\$450,000

Terry High










Renovate Classrooms to LOTE Lab

Repurpose two existing classrooms for Language Other Than English (LOTE) lab. Current classrooms do not meet program requirements.

Budget

\$350,000

Terry High












Renovate Kitchen Serving Lines

Serving lines cannot accommodate student enrollment during lunch periods.

Budget

\$650,000





Install New Student Tracking System

Improve student tracking on bus routes by replacing Zonar System on 300 buses.

Budget

\$500,000





Add Air Conditioning to Existing Buses

Install air conditioning to 101 buses

Budget

\$1,335,000





Purchase 49 New Buses

21 buses to accommodate growth through 2020, and 28 buses for replacement due to age and wear. Buses needed before 2020.

Budget

\$5,175,000



Fulshear

Lamar Campus Transportation Fueling and Tanks to match Fulshear








Remove and Replace Underground Fuel Tanks

Replace four 10,000 gallon diesel/gasoline tanks and one 500 gallon waste oil tank with above ground storage tanks and a new fueling island. Remediate contaminated soil.

Budget

\$900,000

Travis Elementary



Cooler/Freezer location







Replace Walk-in Cooler & Freezer


Cooler and Freezer units have exceeded their useful life.

Budget

\$175,000



Existing Building



Proposed Plan



Replace Auxiliary Locker Room

4,500 sf Auxiliary Locker Room to replace existing nonair-conditioned metal building currently used for visiting teams.


Budget

\$2,200,000




Replace Auxiliary Locker Room











New elevated Press Box with elevator additional seating for press, scouts and guests, enhanced video capability and improved coaching boxes. Current Press Box is undersized and does not meet ADA and current code requirements.

Budget


\$2,800,000






Replace Elevated Press Box







Wertheimer Middle



Possible addition location




New Orchestra Addition

1,680 sf addition to house new middle school Orchestra program.

Budget

\$1,100,000

Wessendorff Middle






New Orchestra Addition

1,680 sf addition to house new middle school Orchestra program.

Budget

\$1,100,000

Wessendorff Middle










Replace Carpet

Carpet has exceeded its useful life.

Budget

\$390,000

Wessendorff Middle










Replace Interior Vinyl Wallcovering

Vinyl Wallcovering has exceeded its useful life.

Budget

\$120,000

Williams Elementary










Replace Carpet

Carpet has exceeded its useful life.

Budget

\$390,000

Williams Elementary










Replace Walk-in Cooler & Freezer

Cooler and Freezer units have exceeded their useful life.

Budget

\$175,000

Williams Elementary





Typical Fire Pump



Install Fire Sprinklers and Fire Pump

Install fire sprinklers to meet current codes.

Budget

\$650,000

